DG Flugzeugbau GmbH
76646 Bruchsal

Technical Note
No. 873/23

Subject	:	Manual revision
Effectivity	:	DG-800B with engine Solo 2 625, all serial numbers
Accomplishment	:	Prior to the next 25 hour inspection but latest prior to the next annual inspection.
Reason	:	1. manual revision 2. the puller assembly W40 was reinforced, if a puller shall be produced, use the new drawing
Instructions	:	Exchange the following manual pages against the new pages issued February 2001, marked TN 873/23 flight manual: 0.2, 0.3, 0.4, 2.7, 4.14, 4.26 maintenance manual: 1a, 2, 3, 4, 4a, 7, 16, 43-46a, 49, 73, 76, 86, 91, enclosure 96, diagram 10a, issued Feb. 2001, drawing W40 issued 30.11.99
Material	:	manual pages see above and drawing W40
Weight and balance	:	influence negligible
Remarks	:	All instructions may be executed by the owner. They have to be inspected and entered in the aircraft logs by a licensed inspector with the next annual inspection.

Bruchsal, date:
February 16. 2001

Author:
Dipl. Ing. Wilhelm Dirks

Type certification
inspector:
Dipl. Ing. Swen Lehner

LBA – approved:

The German original of this TN has been approved by the LBA under the date of *Feb. 26. 2001* and is signed by *Mr. Blume*. The translation into English has been done by best knowledge and judgement.