DG Flugzeugbau GmbH
Postfach 4120 76625 Bruchsal
Tel. 07257/890

Technical Note
No. 873/17

Subject	:	Installation of a disc brake
Effectivity	:	DG-800B with engine SOLO 2625
Accomplishment	:	Optional during production or as retrofit
Reason	:	On customers request
Instructions	:	1. Installation of the hydraulic disc brake and the respective wheel according to working instruction no. 1 for TN 873/17. 2. Exchange and add the following manual pages marked with TN873/17. Please note the marked changes. Flight manual: 0.2, 0.4, 0.5, 4.8, 4.9, 7.14 Maintenance manual: 1, 2, 4, 13, 85, 85a
Material	:	1. material see parts list for working instruction No. 1 for TN 873/17 2. working instruction No. 1 for TN 873/17 3. drawings 8R96, 8R97, 8FW15 4. manual pages see instruction 2
Weight and balance	:	Approx. 1 kg, 2 lbs., influence on centre of gravity negligible
Remarks	:	Instruction No. 1 is to be executed by the manufacturer or by a licensed workshop. Instruction 2 may be executed by the owner. Both instructions have to be inspected and entered in the aircraft logs by a licensed inspector.

Bruchsal, date:
October 25. 1999

Author:
Dipl. Ing. Wilhelm Dirks

LBA – approved:

The German original of this TN has been approved by the LBA under the date of and is signed by Mr. Fendt. The translation into English has been done by best knowledge and judgement.

Type certification inspector:
Dipl. Ing. Swen Lehner